

LSPR Inquiry : Entry # 12**Name**

mike Ecstein

Car Number

670

Submitted By

Co-Driver

Email

dthitta@mtu.edu

Phone

(906) 370-9113

Time Observed

10:46 am

Date Sent

10/15/2021

Event

Lake Superior Performance Rally

Stage/Control

FTC2

Applicable Rule(s)

N/A

Competitor Issue

Need a new rally safe device at first service. Ours is malfunctioning stating we are off and flashes Ok/haz while on stage racing.

Please bring to 670 service crew

Requested Action

Bring new rally safe device to 670 crew in time for first service

Response:

Rally Safe unit function recognized and corrected by ARA Scoring. ARA representative to verify operation at 1st service.

Notes